Risk Assessment Activity – Aerial Trek Course

Pioneer Centre	Assessed by: James Kniffen	Assessed/ Reviewed:	Next Review Date
Centre		09/01/2023	
Reviewed by:	Assist Chief: Max Bishop		10/01/2025
Reviewed by:	Senior Instructors: Andrew Evrard, Joseph Page & Kieran Miles	10/01/2024	
	Lead Instructors: Kieren Plant, Ronan Halpenny & Ruth Gibson		

Overview: The at height (11 metres) obstacle course is purpose built between two towers and was supplied and built by JM Adventure. An annual inspection is carried by High Times Technical Consultants. Regular monthly inspection checks are also carried out on equipment by activities staff as well as a quarterly structural check. A qualified Winter Mountaineering and Climbing Instructor (WMCI) Chief Instructor has overall responsibility. All other instructors are RCI or CWI qualified, or in-house trained using NGB recognized techniques. An examination to check competency of staff is completed on each staff member by the external and independent Technical Advisor. This process is periodically checked and validated by the Technical Advisor and senior staff members do continual monitoring throughout the year. Preferred Staff to Client ratio is 1:12 and a maximum of 1:16 under instruction with a maximum of 16 clients out on the Trek Course at a time.

Hazards	Groups of People at Risk from the Hazards Identified	Probability Severity Risk Category	Control Measures – Reduces the severity and lowers the probability to acceptable levels
Structural Failure	Instructors, staff and guest/participants	Very unlikely	The course built by approved contractors and external annual inspection are carried out. Quarterly structural checks are carried out.
		Fatal	Use of the course is limited to one participant on an element at a time and two
		Medium	participants on a platform and max weight of a participant is 100kg. The
			maximum number of participants on a tower is 15 plus staff on the activity.
Falling objects	Instructors, staff and	Unlikely	Helmets are worn by anyone in the area when activities are being delivered or
	guest/participants		maintenance is being done and guests briefed on how to stand if objects fall to
		Major	protect themselves. All equipment at top of tower secured and emergency
		Medium	procedures in place in case of an accident. Guests advised to remove things
			from pockets or have them stored safely in zipped pockets.

Unauthorized access to Towers	Instructors, staff, guest/participants	Very likely	Tower doors locked and shut when not in use. Only access to towers is via a trained member of staff. No access signs clearly displayed.
access to Towers	and general public	Fatal	a damed member of stam the decess signs crearly displayed.
	and Scheral Papile	Medium	
Rope burns	Instructors, staff and guest/participants	Unlikely	Group briefed on correct clothing. Instructor supervises guests contact with
		Minor	rope.
		Low	
High level fall	Instructors, staff and guest/participants	Very Unlikely	Detailed in-house training & assessments are carried out on activity staff to ensure safe access and practice is used for the activities and the correct use of
		Fatal	all equipment. All PPE is checked and recorded monthly. Clear briefing on accessing the aerial trek course is given and instructors ensure that no one
		Medium	goes out the gate without being clipped into a safety rope. Instructors ensurparticipants are wearing all PPE before partaking in abseiling.
Environmental Hazards	Instructors, staff and guest/participants	Very Likely	All participants are briefed on proper clothing for the current weather conditions. Instructors are issues appropriate PPE waterproof jacket, warm layers, and gloves to use for activity delivery.
		Fatal	Towers not used or sessions cancelled in the event of thunder & lightning (activities can resume 30mins after last thunder sound was heard) and/or winds gusts above 40/45mph (senior staff may reassess and end sessions
		High	 below this level or may let continue if direction is suitable and hazards are managed). Also, further control measures under the Adverse Weather Risk Assessment are to help with environmental hazards.
Slips, trips and falls	Instructors, staff and guest/participants	Likely	Maintenance of site is done by the activities team and maintenance team.
		Minor	Instructors visually check the area upon arrival. General brief and group
		Medium	management is provided by instructors to ensure activities are run safely and guests should follow the no running safety rule when in the activity area.
Soft tissue injury	Instructors, staff and guest/participants	Unlikely	Instructor aware of group's capabilities and encourage group to warm up/warm down as needed.
		Minor	
		Low	

Physiological effects	Guest/participants	Very unlikely Major Medium	Instructors are aware of the group's needs and medical issues. Challenge by choice brief is given and instructors will respect participants choices and be sensitive and adapt to their reactions to the activity they are invited to participate in.
Stress / Panic Attack	Guest/participants	Likely Major or traumatizing High	Challenge by choice brief is given and instructors will respect participants choices. Instructors will air on the side of caution if participants start to panic or have strong emotional reaction to the activity the instructors will react quickly to ensure the level of stress is brought back down to acceptable level. This should help ensure the activity runs well for all those involved.
Small injuries – cuts	Instructors, staff and	Unlikely	The course was sanded down when built, and regularly inspected/maintained
and splinters	guest/participants	nts Minor to prevent cuts and splinters.	to prevent cuts and splinters.
		High	
Entrapment	Instructors, staff and guest/participants	Very Unlikely	Guests briefed as to any dangers of entrapment. Guests stay on one side of
		Major	"spiders web" element to avoid entanglement with lanyard. Guests are on a
		Medium	rope adjusted to a height suitable for them to avoid entrapment issues in obstacle
			elements below them such as hanging ropes etc.
Unconscious	Instructors, staff and	Very Unlikely	Rescue procedures are in place and practice by lead and senior instructors
participant	guest/participants	Major	who would carry out the rescue if needed. Rescue equipment is all set and
		Medium	checked on a monthly basis by lead and senior staff and is accessible at the towers in one of the equipment sheds.